

The Department of Ecology does NOT Warranty the Data and/or the Information on this Well Report.

WATER WELL REPORT

State of Washington

IC Site ID: 7F4

Unique Well ID

Start Card:

Water Right:

(1) OWNER: Name: COVE WATER SYSTEM

Address:

(2) LOCATION OF WELL: Island: Whidbey

Township/Range-Section: 29N/02E-15P

Parcel Number: R22915-040-2400

(2a) Well Address

PWS-ID: 59420R

Source: 1

PWS-Name: Cove Water System

(3) PROPOSED USE: Domestic

(4) TYPE OF WORK: Owner's Well Number (if more than one): 1

Method:

(5) DIMENSIONS: Diameter of Well: inches.

Drilled: feet. Depth of Completed Well: 50 ft.

(6) CONSTRUCTION DETAILS:

Casing Installed: Diam. (in) from to (ft)

Screens: Type Zone Diam Slot from to (ft)

Surface seal: Material: To depth: ft.

(7) PUMP:

Type:

Horsepower:

#Error Land-surface elevation (MSL): 5.510 ft.

AvgWL Elevation: Calc'd Elev: 7 ft.

Earliest Level: ft. below toc Date:

Lastest Level: ft. below toc Date:

Average Level: ft. below toc Average Date:

(9) WELL TESTS:

Type	Yield	Drawdown	After	Date
Pump	6 gpm	feet	hours	12/1/1989

(10) WELL LOG DESCRIPTION:

Material

From
BGS

From
MSL

Thick

RECEIVED
MAR 20 2007
DEPT. OF ECOLOGY

Work Completed:

TD Elev: -43 ft. MSL

WELL CONSTRUCTOR CERTIFICATION:

Name: Unknown

Address:

Contractor's

Registration Number:

Remarks: No well log available. Data obtained from PWS file & DOH report. Reported TRS is out to sea, put well on system owners parcel.

Max CL: 0

Max NO3: 2.3

Generated by the Island County

Hydrogeologic Database: 3/14/2007

Disclaimer: Data presented has been collected from a variety of sources. Island County makes no guarantee as to the validity or accuracy of this data. Please report any errors to the Island County Hydrogeologist



WASHINGTON STATE
DEPARTMENT OF
ECOLOGY

Well Tagging Form

RECEIVED

MAR 20 2007

DEPT. OF ECOLOGY

Unique Well Tag No: AGA612

RECORD VERIFICATION (check ☒ one)

- ☐ Well Report available *(please attach this form to the well report and submit it to the Ecology Regional Office near you)*
- ☐ Verification inconclusive
- ☒ Well Report not available

WELL OWNERSHIP IF DIFFERENT FROM WELL REPORT

Name: Cove Water System

Street Address: 6739 Viewmont Dr

City: Clinton

State: WA

WELL LOCATION IF DIFFERENT FROM WELL REPORT

Well Address: 5962 Cedar St/R22915-040-2400

City: Freelanf

County: Island

T. 29N R. 02E W.M. Sec. 15 SE 1/4 of the SW 1/4

FOR AGENCY USE ONLY

Latitude: 47 59.67982

Longitude: 122 32.45092

Elevation at land surface 6 feet meters (circle one)

Additional Information, if available:

☐ Location marked on topographic map *(please attach)*

☐ Location marked on air photo *(please attach)*



GPS



Topographic Map



Survey



Computer generated



Digital Altimeter



Topographic Map



Other: Computer Generated from

DEM and GPS XY Coordinates

Tag placed and well
GPS'd by:



FOR AGENCY USE ONLY

WELL CHARACTERISTICS

Physical Description of well (size of casing, type of well, housing, etc.)

Pumphouse is Small Blue Cinder Block Building On Right With Address Stamped On It.

Location of Well Identification Tag:

Was supplemental tag needed for easy of identifying well?

☐

Yes

☒

No

If yes, where was tag placed? _____

D	C	B	A
E	F	G	H
M	L	K	J
N	P●	Q	R

SECTION: 29N/02E-15

COMMENTS:

FOR ECOLOGY WATER RESOURCES PROGRAM ONLY

Water Right # _____

Date Issued: _____

Circle One:

Application

Permit

Certificate

Claim

Exempt